

THÔNG BÁO

V.v Tình trạng rung lắc do ảnh hưởng động đất tại Myanmar

Kính gửi Quý Cư dân,

Vào khoảng 13h30 ngày 28 tháng 03 năm 2025, tại TP.HCM đã ghi nhận hiện tượng rung lắc nhẹ, đặc biệt cảm nhận rõ tại các tầng cao (từ tầng 10 trở lên). Theo thông tin chính thức từ Trung tâm Báo tin Động đất và Cảnh báo Sóng thần – Viện Các Khoa học Trái Đất (“Trung tâm”), nguyên nhân do ảnh hưởng từ một trận động đất có độ lớn 7.3 xảy ra vào lúc 13h20'57" (giờ Hà Nội) tại khu vực Myanmar (tọa độ 21.71° vĩ Bắc, 96.02° kinh Đông), với độ sâu chấn tiêu khoảng 10 km và hiện Trung tâm vẫn đang tiếp tục theo dõi diễn biến của trận động đất này.

Theo kết quả kiểm tra sơ bộ, Tòa nhà hiện không ghi nhận bất cứ thiệt hại nghiêm trọng nào, các hệ thống kỹ thuật vẫn đang hoạt động bình thường. Ban Quản lý (“BQL”) vẫn đang tiếp tục tiến hành công tác kiểm tra chi tiết để ghi nhận đầy đủ tình trạng của Tòa nhà và hệ thống Kỹ thuật (MEP). Đồng thời sẽ theo dõi chặt chẽ, phối hợp làm theo sự hướng dẫn của Cơ quan địa phương và sẽ liên tục cập nhật các thông báo chính thức từ các Cơ quan chức năng.

BQL xin lưu ý và khuyến cáo Quý Cư dân vài thông tin, như sau:

- Giữ bình tĩnh, không hoảng loạn và tuân thủ theo hướng dẫn từ BQL và các cơ quan chức năng.
- Hạn chế tối đa việc sử dụng thang máy trong trường hợp nếu có rung lắc xảy ra.
- Trong trường hợp khẩn cấp, vui lòng liên hệ ngay với BQL qua số điện thoại: 0901 890 567 để được hỗ trợ kịp thời.
- BQL sẽ tiếp tục cập nhật các thông tin mới nhất đến Quý Cư dân trong thời gian tới.

BQL rất cảm ơn sự hợp tác và đồng hành của Quý Cư dân trong công tác đảm bảo an toàn cho cộng đồng cư trú tại Tòa nhà.

Mọi ý kiến đóng góp, Quý Cư dân vui lòng liên hệ đến Văn phòng Ban quản lý qua:

- Hotline: 0901 890 567 (Lô G); hoặc
- Địa chỉ email: Sunriseriverside-MO@savills.com.vn.

Trân trọng và cảm ơn.

NOTICE ON

TREMORS DUE TO THE IMPACT OF THE EARTHQUAKE IN MYANMAR

Dear Valued Residents,

At approximately 1:30 PM on 28 March 2025, Ho Chi Minh City experienced mild tremors, particularly noticeable on higher floors (10th floor and above). According to official information from the Center for Earthquake Information and Tsunami Warning - Institute of Earth Sciences ("the Center"), the tremors were caused by the impact of a 7.3 magnitude earthquake that occurred at

1:20:57 PM (Hanoi time) in the Myanmar region (coordinates 21.71° North latitude, 96.02° East longitude), with a focal depth of approximately 10 km. The Center is currently continuing to monitor the development of this earthquake.

According to preliminary inspection results, the Building has not recorded any significant damage, and the technical systems are still operating normally. The Management Office ("MO") is continuing to conduct detailed inspections to fully record the condition of the Building and MEP systems, and will closely monitor, coordinate, and follow the guidance of local authorities as well as continuously update official announcements from authorities.

MO would like to note and recommend the following information to Residents:

- Remain calm, do not panic, and follow instructions from MO and authorities.
- Minimize the use of elevators in case tremors occur.
- In case of emergency, please contact MO immediately at **0901 890 567** for timely support.
- **MO will continue to update the latest information** to Residents in the coming time.

MO greatly appreciates the cooperation and support of Residents in ensuring the safety of the residential community in the Building.

For further comments and feedback, please contact the Management Office:

Hotline: 0901 890 567 (Lot G)

Email: Sunriseriverside-MO@savills.com.vn/

Thanks and Best Regards,

BAN QUẢN LÝ TÒA NHÀ
SUNRISE RIVERSIDE

Mr. Nguyễn Anh Minh – Property Manager

Văn Phòng Quản Lý Sunrise Riverside Lô G. / Sunrise Riverside Lot G Management Office

MANAGEMENT OFFICE
TÒA NHÀ
SUNRISE RIVERSIDE
TP.HCM

SAVILLS VIỆT NAM - MANAGEMENT OFFICE
PHƯỚC KIẾN - NHÀ ĐÈ